Sapphire TB17 - Page 1

Tech Bulletin 17 - Flat Screen Hall Monitor TV

Date Issued: 06/15/09

Product Affected: Sapphire

Version(s) Affected: All Versions

Problem:

Verify Video looks washed out, screen rolls and other general video problems. Ball Camera Video looks fine. CRT TV's and CRT Video Monitors work correctly.

Explanation:

The Video Tuner in some Flat Screen TV's and Video Monitors does not sync up correctly with the Verify Video data out of the Sapphire.

Solution:

- Do not purchase Hall Monitor TV's with Flat Screens that can not be returned to the seller if necessary.
- Test Verify Video quality on all Hall Monitor TV's with Flat Screens prior to installation.